



Roller Extension 20 Field Activity

6/25/19: Fracking on Well #B28 today:



6/14/19: The gearbox on the pumping unit (pumpjack) was off balance and out of alignment which caused the belts to burn off. A pumpjack technician corrected the problem. Well #15 was down for several days to fix this issue which created lighter production for the week.

6/18/19: Well #B28 is currently being drilled, the 12th well in the Roller Extension 20. We will make a call on setting pipe as soon as the well is logged. We will then move forward with completion, which could take up to another 2 weeks.

6/19/19: At 2:00pm, Well #B28 is currently at 1,000' and drilling ahead, possible oil on pits.